



SAFETY NOTICE

The Bombardier snowmobile Shop manual supplement has been prepared in order to assist skilled mechanic's in the efficient repair and maintenance of Bombardier snowmobiles.

Safety features may be impaired if other than genuine Bombardier parts are installed.

Torque wrench tightening specifications must be strictly adhered by. Locking devices must be installed or replaced by new ones, where specified. If the efficiency of a locking device is impaired, it must be renewed.

Never run engine in a closed area. Exhaust fumes contain poisonous carbon monoxide.

Always wear protective clothing (helmet, goggles, boots etc...) when riding vehicle, even for brief periods.

This manual emphasizes particular information denoted by the wording and symbols;

◆ **WARNING:** Identifies and instruction which, if not followed, could cause personal injury.

▼ **CAUTION:** Denotes an instruction which, if not followed, could severely damage vehicle components.

○ **NOTE:** Indicates supplementary information needed to fully complete an instruction.

Although the mere reading of such information does not eliminate the hazard, your understanding of the information will promote its correct use.